

## Cheat Sheet of OnRamp Acronyms

<b>Acronym</b>	<b>Meaning</b>	<b>Relevant Screens/Folders/Reports</b>
APQP	Advanced Product Quality Planning	APQP/PPAP Elements [S1856]; APQP Schedule [R3128]
A/P	Accounts Payable	A/P Aging-Detail Base Curr-Preset Int [R4127]
A/R	Accounts Receivable	A/R Aging Base Curr-Detail-Preset Int. [R4129]; A/R Aging in Base Curr-Sum.-PRESET Int. [R 4130]
ASN	Advanced Shipping Notice	EDI ASN [S1962]; ASN Acknowledgment Report [R3056]; ASN's Not Received [R3152]
BOL	Bill of Lading	Missing Customer BOLs [R4197]
BOM	Bill of Material	BOM Reports [N2369]
CNC	Computer Numerical Control	CNC [N2667]; CNC Screens [N2624]; CNC Reports [N2631]
DCP	Detail Capacity Planning	Detail Capacity Planning (DCP) [N1181]; DCP Applications [N2615]; DCP Reports [N2616]
DSR	Document Storage Retrieval	Document Storage Retrieval [N1223]
EAU	Estimated Annual Usage	Project EAU [N2551]
EDI	Electronic Data Interchange	EDI [N1029]; EDI Incoming Review [N1267]; EDI Outgoing Review [N1268]; EDI Set-Up [N1270]
EOQ	Economic Order Quantity	EOQ Calculator [S2081]
GL	General Ledger	General Ledger & Reports [N1035]
JIT	Just In Time	JIT [N2676]
LS	Line Sequence	Line Sequence [N1179]; Line Sequence Screens [N2602]; Line Sequence Reports [N2604]; Line Sequence Exception Reporting [N2606]; etc.
MDR	Material Deficiency Report	Internal Rejection MDR's [S2375]; Resolve MDR's for Production [S1545]; Open and Close MDR's [R1090]; Late MDR's [R3556]; etc.

MRP	Material Requirement Planning	Material Requirement Planning (MRP) [N1108]
NCR	Non-Conformance Report	Cust Return Inquiry by NCR [S2124]; Late NCRs [R3561]; Submit for NCR (Scrap Operation) [S1905]; NCR Disposition [S1995]; etc.
PM	Preventative Maintenance	Preventative Maintenance [N2628]
PO	Purchase Order	Purchase Orders / Schedules [N1176]; Purchase Order Receiving [N1205]; Non-Production Purchase Orders [N1242]; etc.
PPAP	Production Part Approval Process	Vendor PPAPs [N2500]; PPAP [N1040]; PPAP Master [S1078]; APQP/PPAP Elements [S1856]; etc.
PPM	Parts Per Million	Quality Performance PPM [S2423]; Quality Performance PPM by Customer [R3569]; Vendor PPM [R4334]
PS	Packing Slip	Issue Manual Packing Slip [S1903]; Pending Packing Slips [S2184]; Missing Vendor Packing Slips [R4196]; etc.
QA	Quality Assurance	Parts, With No QA Steps, That Have Demand [R3558]
SO	Sales Order	Sales Order [N1059]; Sales Order Details [N1102]; Sales Orders by Part [S1247]; Sales Order Packaging Instructions [S2292]; etc.
SPC	Statistical Process Control	SPC Reports [N2653]; SPC Feature Info [S2366]; SPC Master [S2390]; SPC Review Data [S2367]; SPC Stats [S2368]; etc.
UM or UOM	Unit of Measurement	UOM Calculator [S2374]
WC	Work Center	Work Centers [N1011]; Work Center Cost Model [N2521]; Work Center Machines [S1018]; Work Center Master [S1019]; etc.
WO	Work Order	Work Orders / Nesting [N1049]; Work Orders [N1064]; Work Order Reports [N1098]; Work Order Review [N1204]; etc.